

Message

From: Cirian, Mike [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=98D0FD2CBB3F4F25B819C6929E18D08D-CIRIAN, MIKE]
Sent: 10/9/2018 3:06:56 PM
To: Coan, Sean [CoanSM@cdmsmith.com]
CC: Gunnar Emilsson [EmilssonGR@cdmsmith.com]
Subject: RE: CFAC Daily Activities - 10/8/2018

Thanks Sean. Sounds like things went well.

Mike

Mike Cirian, PE
Libby On-site Project Manager
US EPA
108 East 9th Street
Libby, MT 59923
(406) 293-6194 Office

From: Coan, Sean [mailto:CoanSM@cdmsmith.com]
Sent: Monday, October 8, 2018 8:31 PM
To: Cirian, Mike <Cirian.Mike@epa.gov>
Cc: Gunnar Emilsson <EmilssonGR@cdmsmith.com>
Subject: CFAC Daily Activities - 10/8/2018

Hi Mike,

The following summarizes field oversight activities for 10/8/2018:

- Reconnaissance was performed on northern surface water feature. No water was present in the entire reach.
- Reconnaissance was performed on the southerly extent of the Cedar Creek Overflow Ditch. Points CFSWP-040 and -041 were dry; -039 contained flowing water.
- Reconnaissance was performed at the South Percolation Ponds peninsula. All points appear to contain water.
- Flow transects were collected at CFSWP-039, -014, and 016.
- Two groundwater sampling crews collected samples at ~7 wells (no oversight performed).
- Rinsate from one of the bladder pumps was sampled.

The plan for tomorrow is to revisit CFSWP-039 for surface water and porewater sampling, and to begin sample collection at points in Cedar Creek. No issues were noted. Feel free to get a hold of me if you have any questions or would like to discuss.

Thanks very much,
Sean M. Coan, PG | Project Manager/Geologist | **CDM Smith** | 50 West 14th Street, Suite 200 | Helena, MT 59601 |
Direct: 406.441.1463 | Cell: 509.336.5691 | coansm@cdmsmith.com | cdmsmith.com